Work Ord Friday, June 04											Page 1
Item ID: Revision ID:	D4035-043			Accept					Setup St	110411101	
Item Name: Start Date: Required Date: Reference:	6/4/2010	start Qty: 2.00 Req'd Qty: 2.00	) 		Cust Item II Customer:	<b>D:</b>	• • •	iki . Pi	S <sub>1</sub>	op	
Approvals:	Process Pla	an;	Date:	Tooling: SPC (Y/N):		te:	t	F			66   18   18   18   18   18   18   18
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr D4035  100  Large Fab  Large Fab	Rev A	<b>Memo</b> 1- Cut D4 2- Drill ho 3- remove	O35-3 as per dwg D4035 oles using DT9563 and chamfe identification marks and debushing in rib and grind weld f	urr	35 SAD 10-0	06-10		2			.06.14
QC Quality Control		QC9- Inspect visual pe	er QSI004- Fusion Welds	0.00				<u> </u>	D 10	06.11	

-

W/O:			V	VOR	K ORDER CHANG	ES					
DATE	STEP	PRO	OCEDURE CI	HANG	E		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
,											
				-	· · · · · · · · · · · · · · · · · · ·				-		
Part No	:	PAR #:	Fault Ca	ategor	y:	_ NCF	R: Yes	No <b>DQ</b>	A:	Date:	
			Disposition:								
NCR:			WORK OR	DER	NON-CONFORMA	ANCE	(NCR	)			
DATE	STEP	Description of NC	Corrective Action Section Initial Action Description			ion B	C: 0	Verific	cation	Approval	Approval
		Section A	Chief Eng		Action Description Chief Eng		Sign & Date	Sect	on C	Chief Eng	QC Inspector
				0							
							- 14 5 7 7 16 1				

#### Work Order ID 59415

Friday, June 04, 2010 8:58:49 AM



Page 2

Item ID:

D4035-043

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Lid Rib Assembly, Aft (350 Basket)

**Start Date:** 

6/4/2010

Start Oty: 2.00

Req'd Qty: 2.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

•				

Process Plan:

Date:

Tooling:

Date:

Run Start

**Required Date: 6/10/2010** 

QC: \_\_\_\_\_ Date:

SPC (Y/N):

Date:

Stop

Sequence ID/ **Work Center ID** 

120

Operation Description

QC5- Inspect part completeness to step on W/O

Set Up/ **Run Hours** 

0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Qty

Reject Number Stamp

Insp.

**Quality Control** 

Memo

Memo

Memo

130

Packaging

Packaging

Identify as per dwg & Stock Location: (WH

0.00

0.00

10-06-14



140

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

10/06/15/99 me 10-6-14

# **Dart Aerospace Ltd**

W/O:			WC	RK ORDER CHANG	GES					\ \ \
DATE	STEP	PRO	OCEDURE CHA	NGE	1	Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				1						
Part No	:	PAR #:	Fault Cate	gory:	NCR:	Yes N	lo <b>DQ</b> /	A:	Date:	
		esolution:								
NCR:		·	WORK ORDI	R NON-CONFORM	IANCE (	NCR)	··			
DATE	STEP	Description of NC	Corrective Action Section E			Verifica			Approval	Approval
DAIL	JILF	Section A	Initial Chief Eng	Action Description Chief Eng	otion Sign & Date			on C	Chief Eng	QC Inspector
									:	
							!			
<u> </u>							-			
	1		1		1		1			

#### **Picklist Print**

Friday, June 04, 2010 8:58:53 AM

Work Order ID: 59415

Parent Item:

D4035-043

Parent Item Name:

Lid Rib Assembly, Aft (350 Basket)

Comments:

IPP revA: new issue DD 09.11.25 verified by:EC

per dwg revA 10.03.15 verified by:EC



IPP Rev:B as

Start Date: 6/4/2010

Required Date: 6/10/2010

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name

D4021-9

Replacement Mfg/ Item ID

Purch Manufactured

Bin Primary Item Location No

Last Location Route Seq ID 100

Unit of Qty on Measure Hand Each

24.0000

Qty per Kit Total Otv 4

Qty Issued Date Status

**Issued** 

Bushing

Location	<u>Lo</u>	c Oty	Loc Co
WA		24	
56094		2	
58404		6	
58701		16	
	100	f	366.8

M304TS0.750W.049

304 SQ Tube .75x.75x.049W

Purchased

No

<u>Code</u>


8280 1.75 3.684211

10-06-16

Location	Loc Oty	Loc Code
MAT	366.8279789	
113763	0	
114323	29.5677289	
114677	37.26025	
114835	300	
MAT017	3.68448E-05	
114298	3.6845E-05	


Dart Ae	rospace	Ltd
---------	---------	-----

W/O:			W	ORK ORDER CHANG	ES			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date C	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	•	PAR #:	Fault Cate	gory:	NCR: Yes	No DQA: _	Date: _	
	Re	esolution:	Dispositio	n:	_ QA: N/C Clo	sed:	Date: _	
NCR:			NCE (NCR)					
DATE	STEP	Description of NC	Description of NC Corrective Action			Verificati	on Approval	Approval
	0,	Section A	Initial Chief Eng	Action Description  Chief Eng	Sign & Date	Section C		QC Inspector
								·
							·	




Dart	Aer	osp	ace	Ltd
------	-----	-----	-----	-----

W/O:			WC	ORK ORDER CHANG	GES			
DATE	STEP	PRO	OCEDURE CHA		Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				,				
						:		
Part No		PAR #:						
	Resc	olution:	Disposition	າ:	_ QA: N/C Cld	osed:	Date: _	
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR	)		
DATE	STEP	Description of NC	· · · · · · · · · · · · · · · · · · ·		tion B	Verification	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
	<u>.</u>							
·				<b>8 8 9 9 9 9 9 9 9 9 9 9</b>	4.4.			




### **Dart Aerospace Ltd**

W/O:			W	ORK ORDER CHANG	ES			
DATE	STEP	PRO	OCEDURE CH		Ву	Date Q1	y Approval Chief Eng / Prod Mgr	Approval QC Inspector
<del>-</del>								
	;							
						į		
Part No	•	PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQA:	Date: _	
		solution:						
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCF	R)		
DATE	STEP	Description of NC		Corrective Action Section		Verificatio	n Approval	Approval
		Section A	Initial Chief Eng	Action Description  Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
	<u></u>							ľ




## **Dart Aerospace Ltd**

W/O:			WC	ORK ORDER CHAN	GES				<del></del>	
DATE	STEP	PRO	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
<del></del>										
										,
Dort No.										
Part No		PAR #:								
		esolution:							Date: _	·
NCR:				ER NON-CONFORM		NCR	) 			-
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Sec Action Description Chief Eng	cription Sign &		Verific Secti		Approval Chief Eng	Approval QC Inspector
			Onioi Eng	Officer Eng		Date				
		. ·								
		,								



Dart	Aer	osp	ace	Ltd
------	-----	-----	-----	-----

W/O:			W	ORK ORDER CHAN	GES					
DATE	STEP	PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	
Part No	:	PAR #:	Fault Cate	egory:	NCR: \	'es N	lo <b>DQA</b>	:	Date:	ate:ate:
	Resc	olution:	Dispositi	on:	QA: N/	C Clos	sed:		Date: _	
NCR:		,	WORK ORD	ER NON-CONFORM	MANCE (N	ICR)				
DATE	STEP	Description of NC Section A	Corrective Action S Initial Action Descriptio Chief Eng Chief Eng		Section B  on Sign & Date		Verification Section C		Approval Chief Eng	
			O.Hor Ellig	Office Ling		ate				
									:	
									-	



Dart Ae	rospace	Ltd								te 🕡 👉 e 🗣
W/O:				WORK ORDER	CHANGES					
DATE	STEP		PR	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							ju			
Part No	) <b>:</b>		PAR #:	Fault Category:	NC	R: Yes	No <b>D</b>	QA:	Date: _	
	Re	esolution:		Disposition:	QA	: N/C (	Closed: _		Date: _	
NCD:			,	WORK ORDER NON-COM	IFORMANCE	= (NC	R)		,	

NCR: WORK ORDER NON-CONFORMANCE (NCR)								
DATE ST		Description of NC Section A		Corrective Action Section B	Vididi			
	STEP		Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
		<b>«</b>	•	,	-			
				, ,				
•				. <b>3</b> <sup>1</sup> /				
		•		•				
	-							
								÷.